

Pipe

<i>Filename of original image</i>	<i>Page</i>
Pipe 2.tif	2
Pipe 12.tif	3
Pipe 16.tif	4
Pipe 20.tif	5
Pipe 11.tif	6
Pipe 19-21.tif	7

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 2 PIPEARCHITECTCONTRACTORORIGINAL OWNER Wm. B. Collins (?)ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL metal horizontal siding recently applied over ??SIGNIFICANCE none - limited

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 12 PIPEARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c1898-1908BUILDING MATERIAL red brick, brick lintelsSIGNIFICANCE none

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 16 PIPEARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1898-1908BUILDING MATERIAL red brick - brick lintelsSIGNIFICANCE none

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 20 PIPEARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900-1910 various changes during yearsBUILDING MATERIAL stjucoSIGNIFICANCE none

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE


LOCATION 11 PIPEARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1875BUILDING MATERIAL metal gorizontal siding recently applied over???SIGNIFICANCE none - limited

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORY

BLOCK No.
ITEM.

PAGE

LOCATION 19-21 PIPE

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single dwellings abutting - made into two units

DATE OF CONSTRUCTION #21 about 1870
#19 about 1880

BUILDING MATERIAL horizontal siding recently applied aover ???

SIGNIFICANCE none



PHOTO DATE: 17-1-75