Sultan

Filename of original image	Page
Sultan 20.tif	2
Sultan 22-24.tif	3
Sultan 17.tif	4

ARCHITECTURAL INVENTORY

BLOCK No. PAGE ITEM.

LOCATION 20 SOCTAN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE KXXXXX single family dwelling

DATE OF CONSTRUCTION c.1883

BUILDING MATERIAL

recently covered with horizontal metal siding over stucco(?)

SIGNIFICANCE none



PHOTO DATE: 11-12-74

ARCHITECTURAL INVENTORY

BLOCK No. PAGE ITEM.

LOCATION ZZ-ZY SUCTAN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE two unit dwelling

DATE OF CONSTRUCTION c.1880 or earlier

BUILDING MATERIAL stucco

SIGNIFICANCE Priority #5. Front has a degree of statinction.



PHOTO DATE: 11.12-74

ARCHITECTURAL INVENTORY

BLOCK No. PAGE ITEM.

LOCATION 17 SUCTAN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER Bradley

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1870

BUILDING MATERIAL stucco

SIGNIFICANCE none



1-8.74 PHOTO DATE: