John

Filename of original image	Page
John 12.tif	2
John 14.tif	3
John 22.tif	4
John 30.tif	5
John 11.tif	6
John 15.tif	7
John 21.tif	8
John 29.tif	9

BLOCK No. ITEM.

PAGE

LOCATION 12 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE

single family dwelling

DATE OF CONSTRUCTION

1870 or earlier

BUILDING MATERIAL

imitation stone siding over frame or stucco

SIGNIFICANCE

Priority #4. Age, character. Could be very well restored.



PHOTO DATE: 22.7-74

BLOCK No. PAGE ITEM.

LOCATION 14 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1914

BUILDING MATERIAL red brick

SIGNIFICANCE none



PHOTO DATE: 22-7-14

BLOCK No. PAGE

LOCATION 22 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1880

BUILDING MATERIAL recently resided over stucco or frame

SIGNIFICANCE Priority #4. Age, good restoration



BLOCK No. PAGE ITEM.

LOCATION 30 JOHN

ARCHITECT

CONTRACTOR


ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1880

BUILDING MATERIAL frame or stucco now recetly covered with brick

SIGNIFICANCE Limited - age



BLOCK No. PAGE ITEM.

LOCATION 11 SOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1875

BUILDING MATERIAL frame covered with recent siding

SIGNIFICANCE Priority #4. Age, style, good condition.



BLOCK No. PAGE ITEM.

LOCATION /5 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION

1922-26

BUILDING MATERIAL tan brick

SIGNIFICANCE

none



PHOTO DATE: 30.11.74

BLOCK No. PAGE ITEM.

LOCATION 21 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1870-75

BUILDING MATERIAL frame or sutucco covered with siding

SIGNIFICANCE

limited - age



BLOCK No. PAGE ITEM.

LOCATION 29 JOHN

ARCHITECT

CONTRACTOR

ORIGINAL OWNER John Watkin

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION

1875

BUILDING MATERIAL

frame, now covered with stucco

SIGNIFICANCE

limited - age

