

Palmer

<i>Filename of original image</i>	<i>Page</i>
Palmer 23-25.tif	2
Palmer 27-29.tif	3
Palmer 33-35.tif	4
Palmer 45.tif	5
Palmer 55.tif	6
Palmer 107.tif	7
Palmer 151.tif	8
Palmer 177.tif	9
Palmer 179.tif	10
Palmer 279.tif	11
Palmer 6-8.tif	12
Palmer 10.tif	13
Palmer 40.tif	14
Palmer 84.tif	15
Palmer 112.tif	16
Palmer 122.tif	17
Palmer 126.tif	18
Palmer 128.tif	19
Palmer 144.tif	20
Palmer 154.tif	21
Palmer 162.tif	22
Palmer 164.tif	23
Palmer 168.tif	24
Palmer 280.tif	25

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 23-25 Palmer street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION 1875 or as early as 1865BUILDING MATERIAL imitation brick composition siding over stuccoSIGNIFICANCE priority #5 With 27-29 and 33-35 form interesting group of workmen's cottages.

PHOTO DATE: 24. 12. 74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 27-29 Palmer street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two family dwellingDATE OF CONSTRUCTION 1865-1873BUILDING MATERIAL stuccoSIGNIFICANCE Priority #5. With 23-25 and 33-35 form an interesting group of wokemn's cottages of period.

PHOTO DATE: 24.12.74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 33-35 Palmer street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION 1865-1873BUILDING MATERIAL stuccoSIGNIFICANCE Priority #5. With 23-25 and 27-29 form an interesting group of workmen's cottages of the period.

PHOTO DATE: 24-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 45 Palmer street, south side, SW corner Queen (sz Queen)ARCHITECTCONTRACTORORIGINAL OWNER Wm. Burgess, photographerORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL stone basment floor, stucco aboveSIGNIFICANCE Priority #4. Age, character.

PHOTO DATE: 2-4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 55 PALMERARCHITECTCONTRACTORORIGINAL OWNER Colonel A. H. MacDonaldORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1894-96BUILDING MATERIAL red brick, stone lintels and sills
decorated corniceSIGNIFICANCE Priority #4. Distinctive style. One of better
examples of mid-1890's in city.

PHOTO DATE: 2-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 107 Palmer street, south side, Between Staart-MetcalfARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1885-1895BUILDING MATERIAL yellow brickSIGNIFICANCE limited

PHOTO DATE: 31-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 151 Palmer street, south side, between Metcalf-JacksonARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1914-1915BUILDING MATERIAL red brick and stucco gable endsSIGNIFICANCE limited

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 177 Palmer street, south side, SW corner JacksonARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1917-1918BUILDING MATERIAL sidingSIGNIFICANCE none

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 179 PALMERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1918-20BUILDING MATERIAL red brickSIGNIFICANCE limited

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 279 PALMER ST.ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1880BUILDING MATERIAL metal siding over stucco-frameSIGNIFICANCE limited

PHOTO DATE: 2-6-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 6-8 Palmer north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION 1860'sBUILDING MATERIAL local limestone, paintedSIGNIFICANCE Priority #3. stone construction, age, type.

PHOTO DATE: 11-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 10 ~~Palmer~~ street, north side, NW corner King
Palmer

ARCHITECTCONTRACTORORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1885-1895

BUILDING MATERIAL stucco, stone foundation

SIGNIFICANCE Priority #4. Character.



PHOTO DATE: 24.12.79

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 40 Palmer street, north side, NW corner QueenARCHITECTCONTRACTORORIGINAL OWNER James Innes, M.P., Proprietor "Mercury"ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1860'sBUILDING MATERIAL local limestoneSIGNIFICANCE Priority #1. stone construction, age, character,
some historic associations.

PHOTO DATE: 24.12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 84 Palmer street, north side Between Quen and StuartARCHITECTCONTRACTORORIGINAL OWNER Dr. D. F. FosterORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1895BUILDING MATERIAL pressed red brick
stone lintels and sillsSIGNIFICANCE limited

PHOTO DATE: 11-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 112 Palmer street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL painted brickSIGNIFICANCE limited to street unity

PHOTO DATE: 31-12-79

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 122 Palmer street, north sideARCHITECTCONTRACTORORIGINAL OWNER Mrs. Anne JohnstonORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL local limestoneSIGNIFICANCE Priority #2. Stone construction, Character, condition tyle.

PHOTO DATE: 5.12.73

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 128 Palmer street, north side, SE cõner St. CatharinesARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900 or earlierBUILDING MATERIAL composition siding , imitation brickSIGNIFICANCE ~~limited~~ limited

PHOTO DATE: 5.12.73

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 128 PALMERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1905-1913BUILDING MATERIAL brick and stuccoSIGNIFICANCE limited

PHOTO DATE: 31-12-74

ARCHITECTURAL INVENTORYBLOCK No. PAGE
ITEM.LOCATION 144 Palmer street, north side, NW corner MetcalfARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1885-1895BUILDING MATERIAL painted brick (may be two color under paint)SIGNIFICANCE limited - might be Priority #5. Fine elements of style and character.

PHOTO DATE: 5.12.73

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 154 Palmer street, north side NE corner MetcalfARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880-1885BUILDING MATERIAL yellow brickSIGNIFICANCE Priority #4, Character, style, good conditioj.

PHOTO DATE: 31/12.74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 162 Palmer street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1908-1913BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 164 Palmer street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1905-1913BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 168 Palmer street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single famly dwellingDATE OF CONSTRUCTION 1905-1913BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 280 Palmer street, north side, between Lane - StevensonARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain probably 1840'sBUILDING MATERIAL LogSIGNIFICANCE The only surviving log house in the city with logs exposed. Very close to original condition, well maintained. Priority #1.

PHOTO DATE: 5/12/73