

Elora

<i>Filename of original image</i>	<i>Page</i>
Elora 9.tif	2
Elora 11.tif	3
Elora 21.tif	4
Elora 25.tif	5
Elora 29.tif	6
Elora 45.tif	7
Elora 14.tif	8
Elora 18.tif	9
Elora 22.tif	10
Elora 26.tif	11
Elora 30.tif	12
Elora 34.tif	13
Elora 38.tif	14
Elora 42.tif	15
Elora 46.tif	16

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 9 Elora street, north sideARCHITECT -CONTRACTOR -ORIGINAL OWNER - John SmithORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1922-23SIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 28-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION LL Elora street, north sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 19~~05~~-1920SIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 10-1-75

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 21 Elora Street, north sideARCHITECT -CONTRACTOR -ORIGINAL OWNER RobinsonORIGINAL USE single dwelling residenceDATE OF CONSTRUCTION about 1870'sSIGNIFICANCE Priority #4. This is probably the oldest house in the area. It retains considerable character.BUILDING MATERIAL - stucco

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION ~~126~~ 25 Elora street, north sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 19~~05~~-1920SIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 10-1-75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 29 Elora street, north sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 19~~15~~-1920SIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 3.2.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION *% 45 Elora street, north side corner ClintonARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890'sSIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 14 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority - 4 or 5, Grouping with 2 others similarBUILDING MATERIAL red brick with stone trim

PHOTO DATE 28-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 18 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority 4 or 5, Grouping with 8 other similar units.BUILDING MATERIAL red brick with stone trim

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 22 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority 4 or 5, Grouping with 8 other similar unitsBUILDING MATERIAL red brick with stone trim

PHOTO DATE 10-1-75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 26 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority 4 or 5. Grouping related to 8 similar unitsBUILDING MATERIAL red brick with stone trim

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 30 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority 4 or 5, Grouping with 8 other similar unitsBUILDING MATERIAL

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 34 Elora street, south side

ARCHITECT -

CONTRACTOR -

ORIGINAL OWNER -

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1900

SIGNIFICANCE priority 4 or 5. Grouping with other 8 similar units.

BUILDING MATERIAL



PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION #* 38 Elora street, south side

ARCHITECT -

CONTRACTOR -

ORIGINAL OWNER -

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1900

SIGNIFICANCE Priority 4 or 5. Grouping with 8 other simular units.

BUILDING MATERIAL red brick with stone trfm.



PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 42 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority 4 or 5, Grouping with 8 similar units.BUILDING MATERIAL red brick with stone trim

PHOTO DATE 10.1.75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 46 Elora street, south sideARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900SIGNIFICANCE Priority ~~4 or 5~~ 4 or 5. Grouping with 8 similar units.BUILDING MATERIAL red brick with stone trim

PHOTO DATE 10.1.75