

Park

<i>Filename of original image</i>	<i>Page</i>
Park 10.tif	2
Park 14.tif	3
Park 20.tif	4
Park 24-26.tif	5
Park 28.tif	6
Park 34.tif	7
Park 40.tif	8
Park 46.tif	9
Park 50.tif	10
Park 54.tif	11
Park 60-62.tif	12
Park 64.tif	13
Park 7.tif	14
Park 11.tif	15
Park 15.tif	16
Park 25.tif	17
Park 29.tif	18
Park 35.tif	19
Park 39.tif	20
Park 45.tif	21
Park 49.tif	22
Park 55-57.tif	23
Park 63.tif	24
Park 71.tif	25

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 10 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNER Robert BarberORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1895BUILDING MATERIAL pressed red brickSIGNIFICANCE priority #4 or 5. Street grouping

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 14 Park Avenue , west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION mid ~~1890's~~ 1870'sBUILDING MATERIAL painted brickSIGNIFICANCE Priority ~~XX~~ #4. Age, character, street relationship

PHOTO DATE: 17-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 20 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c1880BUILDING MATERIAL pale yellow brick, brick lintelsSIGNIFICANCE Priority #4 or #5. Street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 24-26 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION about 1900BUILDING MATERIAL red brick with stone lintels and sills, bracketed cornice.SIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 28 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1898-1900BUILDING MATERIAL red brick stone lintels and sillsSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION

34 Park Avenue, west side

ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE

single family dwelling

DATE OF CONSTRUCTION

1922-26

BUILDING MATERIAL

brick

SIGNIFICANCE

Limited - street unity



PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 40 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1898-1908BUILDING MATERIAL red brick with brick lintelsSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 46 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1898-1908BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 50 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1898-1908BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 54 Park Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNER Wm. A. KnowlesORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1898-1908BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 60 Park Avenue, west side
(62)ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1903 - 1913BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE Priority "5; street unity

PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

(62)
LOCATION 64 Park Avenue, west side

ARCHITECTCONTRACTORORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1900-1910

BUILDING MATERIAL red brick with stone lintels and sills

SIGNIFICANCE Priority #4 or #5; street unity.



PHOTO DATE: 17-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 7 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1870-1875 or earlierBUILDING MATERIAL local limestoneSIGNIFICANCE Priority #2. Age, character, stone construction.

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 11 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1870 or earlierBUILDING MATERIAL imitation brick composition sidingSIGNIFICANCE Limited

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 15 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single fa mily dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL painted brickSIGNIFICANCE Limited

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 25 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNER ~~Mrs. M. Snyder~~ Knox Presbyterian Church ManseORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1895-1905BUILDING MATERIAL red brick, brick lintels, stone foundationSIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c 1900-1910BUILDING MATERIAL red brick, stone lintels and sillsSIGNIFICANCE Priority #5, street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 35 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1910-1914BUILDING MATERIAL brickSIGNIFICANCE Priority #5; street unity

PHOTO DATE: 17-1-78

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 39 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1904-1913BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE Priority #5: street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 45 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNER H. MahoneyORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1908BUILDING MATERIAL red brick with stone lintels and sillsSIGNIFICANCE priority #4 or #5; street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 49 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL redbrick, stone lintels and sills, bracketed eaves.SIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION ~~55~~ 57 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit
~~single family dwelling~~DATE OF CONSTRUCTION 1898-1904BUILDING MATERIAL red brick, brick lintels.SIGNIFICANCE Priority #4 or #5; street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 63 Park Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNER ~~James G. Keleher, clothing merchant~~ J.H. McCraeORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1894-1896BUILDING MATERIAL red brick and frameSIGNIFICANCE Priority #4; street unity

PHOTO DATE: 27-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 71 Park Avenue, east side SE corner London RoadARCHITECTCONTRACTORORIGINAL OWNER James C. Keleher, clothing merchantORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1894-1896BUILDING MATERIAL pressed red brickSIGNIFICANCE Priority #4; street unity

PHOTO DATE: 27-11-74