

Chadwick

<i>Filename of original image</i>	<i>Page</i>
Chadwick 21.tif	2
Chadwick 6.tif	3
Chadwick 22.tif	4
Chadwick 24.tif	5

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 21 CHADWICKARCHITECT -CONTRACTOR -ORIGINAL OWNER - Mrs. CoalyerORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 4.1.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 6 CHADWICK AvenueARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain c.1920'sBUILDING MATERIAL brick section to rear, front: recently covered
with metal siding over (???)SIGNIFICANCE nonePHOTO DATE: 10.1.75
~~30.11.8~~

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 22 CHADWICK (130)ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain - about 1890- 1900BUILDING MATERIAL metal siding over (???)SIGNIFICANCE Priority #4. Character, grouping in areaPHOTO DATE: 4-1-75
~~3-1-75~~

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 24 CHADWICKARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1875-1885BUILDING MATERIAL recently covered with imitation white brick
vener.SIGNIFICANCE Priority #4. Character and related grouping in area.

PHOTO DATE: 4.1.75