

Green

<i>Filename of original image</i>	<i>Page</i>
Green 4.tif	2
Green 10.tif	3
Green 14.tif	4
Green 16.tif	5
Green 20.tif	6
Green 22-24.tif	7
Green 28.tif	8
Green 32.tif	9
Green 36-38.tif	10
Green 42.tif	11
Green 50.tif	12
Green 54.tif	13
Green 56.tif	14
Green 60.tif	15
Green 62.tif	16
Green 11.tif	17
Green 19.tif	18
Green 21-23.tif	19
Green 25-27.tif	20
Green 31.tif	21
Green 37-39.tif	22
Green 45.tif	23
Green 49.tif	24
Green 59.tif	25

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 10 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1900-1910BUILDING MATERIAL red brickSIGNIFICANCE Limited- relationship to total street-scape

PHOTO DATE: 2-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 14 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1910-1920BUILDING MATERIAL brickSIGNIFICANCE Limited - relationship to total street-scape

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 16 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1874BUILDING MATERIAL stucco covered with brick veneerSIGNIFICANCE Priority #4: the relationship to total street-scape.

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 20 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1873-4BUILDING MATERIAL stucco covered with imitation brickSIGNIFICANCE Priority #4 ; the relationship to total street-scape.

PHOTO DATE: 25.7.74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 22-24 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION c.1874BUILDING MATERIAL rough cast covered with yellow brickSIGNIFICANCE Priority #4. relationship to total street-scape.

PHOTO DATE: 25.7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 2B GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION late 1860's (before 1873)BUILDING MATERIAL local limestoneSIGNIFICANCE Priority #2. Stone construction, good character, style.

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 32 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1900BUILDING MATERIAL red brickSIGNIFICANCE Priority #5, relationship to total street-scape.PHOTO DATE: 25.7.74
~~14.6.74~~

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 36-38 GREENARCHITECTCONTRACTORORIGINAL OWNER Levi Cossit, proprietor Cossit's Implement Works.ORIGINAL USE ~~Probably~~ ^{one} unit dwelling, but may have been converted later, to two.DATE OF CONSTRUCTION ~~1890s or earlier (may have been moved to this location)~~ c.1870BUILDING MATERIAL brick veneer over stucco.SIGNIFICANCE Priority #5. relationship to total street-scape.

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 42 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1874BUILDING MATERIAL stucco covered with red brick veneerSIGNIFICANCE Priority #4: relationship to total street-scape.

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 50 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1873-75BUILDING MATERIAL stucco covered recently with white brick veneer.SIGNIFICANCE Priority #4 - relationship to total street-scape.

PHOTO DATE: 25.7.74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 54 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL stuccoSIGNIFICANCE Priority #5. Total grouping

PHOTO DATE: 25-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 56 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870-74BUILDING MATERIAL stuccoSIGNIFICANCE Priority #5. Relationship to total street-scape.

PHOTO DATE: 28.7.79

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 60 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL stuccoSIGNIFICANCE limitedPHOTO DATE: 25.7.74
20.61.74

ARCHITECTURAL INVENTORYBLOCK No. PAGE
ITEM.LOCATION 62 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL recent siding over (?) stucco-frameSIGNIFICANCE Priority #5, relationship to street-scape

PHOTO DATE: 25.7.74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 11 Green street, north sideARCHITECTCONTRACTORORIGINAL OWNER George MertonORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1874-75SIGNIFICANCE Priority #1 . Stone construction, fine style and character, fine door treatment.BUILDING MATERIAL - local limestone

PHOTO DATE 28.7-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 19 Green street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1858-64SIGNIFICANCE Priority #1. One of the finest stone cottages in the city. Front of very carefully dressed ashlar courses.BUILDING MATERIAL - local limestone, dressed ashlar facade

PHOTO DATE 25.7.74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 23-21 Green street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION 1900-1910SIGNIFICANCE noneBUILDING MATERIAL red brick

PHOTO DATE 25.7.74

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 25 -27 Green street, north side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE two unit dwelling

DATE OF CONSTRUCTION 1870-74

SIGNIFICANCE Priority #2. stone construction, character.
Stone grouping on street.

BUILDING MATERIAL - local limestone



PHOTO DATE 25.7.74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 31 Green street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1870 or earlierSIGNIFICANCE Priority #4. character, style, condition.BUILDING MATERIAL - clapboard, frame

PHOTO DATE 25.7-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION37-39
~~39~~

Green street, north side

ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION c.1870-75SIGNIFICANCE Priority #3. Retains good original porches and bow windows. Could be given more sympathetic restoration.BUILDING MATERIAL - pale yellow brick

PHOTO DATE 25.7.74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 45 Green street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1900SIGNIFICANCE limited - part of total street-scapeBUILDING MATERIAL red brick with stone trim.

PHOTO DATE 25.7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 49 GREENARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL red brickSIGNIFICANCE Priority #4. Unity of total street.

PHOTO DATE: 25.7.74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 59 Green street (Emma Place) north sideARCHITECTCONTRACTORORIGINAL OWNER Chalmers Presbyterian Church (Manse)ORIGINAL USE Manse Chalmer's Church, single family dwellingDATE OF CONSTRUCTION c.1867SIGNIFICANCE Priority #1. Very fine stone 'mansion' in good condition, fine character and style. Well restored.BUILDING MATERIAL local limestone

PHOTO DATE 25.7-74