

Victoria South

| <i>Filename of original image</i> | <i>Page</i> |
|-----------------------------------|-------------|
| Victoria South 146.tif | 2 |
| Victoria South 170.tif | 3 |
| Victoria South 143.tif | 4 |
| Victoria South 145.tif | 5 |
| Victoria South 147.tif | 6 |
| Victoria South 149.tif | 7 |
| Victoria South 151.tif | 8 |
| Victoria South 153.tif | 9 |
| Victoria South 205.tif | 10 |
| Victoria South 207.tif | 11 |
| Victoria South 209.tif | 12 |
| Victoria South 211.tif | 13 |
| Victoria South 213.tif | 14 |
| Victoria South 215.tif | 15 |
| Victoria South 217.tif | 16 |
| Victoria South 219.tif | 17 |
| Victoria South 221-223.tif | 18 |
| Victoria South 225.tif | 19 |
| Victoria South 227.tif | 20 |
| Victoria South 229.tif | 21 |
| Victoria South 231.tif | 22 |
| Victoria South 233.tif | 23 |
| Victoria South 235.tif | 24 |
| Victoria South 237.tif | 25 |
| Victoria South 239.tif | 26 |
| Victoria South 241.tif | 27 |
| Victoria South 243.tif | 28 |
| Victoria South 245.tif | 29 |
| Victoria South 247.tif | 30 |
| Victoria South 249.tif | 31 |
| Victoria South 251.tif | 32 |
| Victoria South 253.tif | 33 |

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 146 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain - about 1910-20BUILDING MATERIAL red brickSIGNIFICANCE nonePHOTO DATE: 3-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 170 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain. Possibly 1920'sBUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 3. 2. 75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 143 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1885-1895BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 3-2-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 145 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1911-1913BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 3-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 147 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910-12BUILDING MATERIAL frame sidingSIGNIFICANCE none

PHOTO DATE: 3-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 149 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910-12BUILDING MATERIAL frame sidingSIGNIFICANCE none

PHOTO DATE: 3-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 151 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910-12BUILDING MATERIAL brick veneer (over frame siding?)SIGNIFICANCE none

PHOTO DATE: 3-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 153 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1915-20BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 3.2.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 205 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 207 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 209 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1912 -14BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 21¹/₂ VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1905-1912BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 213
213 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1926-27BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 215 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 23-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 217 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1910BUILDING MATERIAL stucco covered with metal sidingSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 219 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1910BUILDING MATERIAL stuccoSIGNIFICANCE nonePHOTO DATE: 32
23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 221-3 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION c.1905-1915BUILDING MATERIAL stucco sides, siding on frontSIGNIFICANCE none

PHOTO DATE: 23-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 225 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1926-22BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 227 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1922-23BUILDING MATERIAL sidingSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 229 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain date: ~~1920s~~ about 1910-15BUILDING MATERIAL sidingSIGNIFICANCE none

PHOTO DATE: 23.1.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 231 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1918 per some records, appearance of 1940'sBUILDING MATERIAL sidingSIGNIFICANCE none

PHOTO DATE: 23.1.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 233 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE originally a store moved from York RoadDATE OF CONSTRUCTION c.1916-18BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 235 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1922-23BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23.1.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 237 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1918BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 239 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1921BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 241 VICTORIAARCHITECTCONTRACTORORIGINAL OWNER G. Issac ZettleORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1925-26BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 243 VICTORIAARCHITECTCONTRACTORORIGINAL OWNER Wm. BellORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1922-2BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 245 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1926-27BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 247 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1927BUILDING MATERIAL metal sidingSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 249 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1926-27BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 251 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USEDATE OF CONSTRUCTIONBUILDING MATERIALSIGNIFICANCE

PHOTO DATE: 23-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 253 VICTORIAARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION about 1926-27BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 23-1-75