Galt

| Filename of original image | Page |
|----------------------------|------|
| Galt 3.tif | 2 |
| Galt 7-9.tif | 3 |
| Galt 19.tif | 4 |
| Galt 23.tif | 5 |
| Galt 35.tif | 6 |
| Galt 43.tif | 7 |
| Galt 47.tif | 8 |
| Galt 40.tif | 9 |
| Galt 52-54.tif | 10 |
| Galt 62-64.tif | 11 |
| Galt 66-68.tif | 12 |
| Galt 70-72.tif | 13 |
| Galt 74.tif | 14 |
| Galt 80.tif | 15 |

BLOCK No. PAGE ITEM.

LOCATION 3 GALT

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1875 ir earlier

BUILDING MATERIAL stucco

SIGNIFICANCE none



PHOTO DATE: 9. 2. 74

BLOCK No. PAGE ITEM.

LOCATION 7-9 GALT

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1876-1880

BUILDING MATERIAL painted brick

SIGNIFICANCE none



PHOTO DATE: 9. 7. 74

BLOCK No. PAGE ITEM.

LOCATION 19 Galt Street

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1900

BUILDING MATERIAL red brick

SIGNIFICANCE none



PHOTO DATE: 2-6-75

BLOCK No. PAGE ITEM.

LOCATION 23 GALT

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1881-82

BUILDING MATERIAL red brick with stone trim

SIGNIFICANCE limited



PHOTO DATE: 9-2-74

BLOCK No. PAGE ITEM.

LOCATION 35 GALT

ARCHITECT

CONTRACTOR Walter Grierson

ORIGINAL OWNER Probably Walter Grierson, stone cutter.

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1870

BUILDING MATERIAL local limestone (brick for rear kitchen)

SIGNIFICANCE Priority #1. Stone construction, age, material. grouping.



PHOTO DATE: 4.2.74

BLOCK No. ITEM. PAGE

LOCATION 43 GALT

ARCHITECT

CONTRACTOR Walter Grierson

ORIGINAL OWNER Probably Walter Grierson, stone cutter (or P.W. Cooper)

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1870 (stone kitchen wing to rear: later)

BUILDING MATERIAL local limestone

SIGNIFICANCE Priority #1. Stone construction, grouping, age, character.



PHOTO DATE: 25.8.72

BLOCK No. PAGE ITEM.

LOCATION 47 GALT

ARCHITECT

CONTRACTOR Walter Grierson

ORIGINAL OWNER Walter Grierson, stone cutter.

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1870 (later addition to rear)

BUILDING MATERIAL local limestone.

SIGNIFICANCE Priority #1 Stone construction, grouping, age, character



25.8.72 PHOTO DATE: 35 GALT 13.122.74 14 26.12.74

BLOCK No. PAGE ITEM.

LOCATION 40 Galt Street

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1875 or earlier (Possibly bricked later)

BUILDING MATERIAL pressed red brick

SIGNIFICANCE none



PHOTO DATE: 2-6-75

BLOCK No. PAGE ITEM.

LOCATION 52.54 GALT

ARCHITECT

CONTRACTOR probably Walter Grierson

ORIGINAL OWNER

ORIGINAL USE two unit dwelling

DATE OF CONSTRUCTION 1870-1874

BUILDING MATERIAL local limestone

SIGNIFICANCE Priority #1. Stone construction, grouping, age, character.



PHOTO DATE: 21.8.72

ARCHITECTURAL INVENTORY Block No. Page

Item.

LOCATION 62-64 GALT STREET (Two houses)

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE

single family dwellings

DATE OF CONSTRUCTION Both: C.1900=1910

SIGNIFICANCE none

BUILDING MATERIAL Both: pressed red brick



PHOTO DATE 24-6-74

Block No. Page

Item.

LOCATION 66-68 GALT STREET

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION XXXXXXX c.1890-190X0

SIGNIFICANCE none

BUILDING MATERIAL IMITATION BRICK SIDING



PHOTO DATE 24-6-74

Block No. Page

Item.

LOCATION 70-72 GALT STREET

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1900

SIGNIFICANCE

hone

BUILDING MATERIAL red brick



PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY Block No. Page

Item.

LOCATION 74 GALT STREET

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1923-25

SIGNIFICANCE

BUILDING MATERIAL - red brick



PHOTO DATE 24-6-74

Block No. Page Item.

LOCATION BO GALT STREET

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1890

SIGNIFICANCE none

BUILDING MATERIAL Stucco



PHOTO DATE 24-6-74