

Inkerman

<i>Filename of original image</i>	<i>Page</i>
Inkerman 11.tif	2
Inkerman 21.tif	3
Inkerman 25.tif	4
Inkerman 35.tif	5
Inkerman 41.tif	6
Inkerman 47.tif	7
Inkerman 71.tif	8
Inkerman 77.tif	9
Inkerman 85.tif	10
Inkerman 87.tif	11
Inkerman 91.tif	12
Inkerman 6.tif	13
Inkerman 12.tif	14
Inkerman 16.tif	15
Inkerman 18.tif	16
Inkerman 22.tif	17
Inkerman 28.tif	18
Inkerman 36.tif	19
Inkerman 40.tif	20
Inkerman 42.tif	21
Inkerman 44.tif	22
Inkerman 46.tif	23
Inkerman 48.tif	24
Inkerman 74.tif	25
Inkerman 80.tif	26
Inkerman 82.tif	27
Inkerman 84.tif	28
Inkerman 100.tif	29
Inkerman 156.tif	30
Inkerman 160.tif	31

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 11 Inkerman street, north sideARCHITECT noneCONTRACTOR Brock ClarkORIGINAL OWNER Mrs. L. M. CoulingORIGINAL USE single family dwellingDATE OF CONSTRUCTION 192 2-23SIGNIFICANCE noneBUILDING MATERIAL - red brick

PHOTO DATE 10-1-75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 21 Inkerman street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870SIGNIFICANCE noneBuilding material - siding over stucco

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 25 Inkerman street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870SIGNIFICANCE noneBUILDING MATERIAL - stucco recently covered with siding

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 35 Inkerman Street, north side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1875

SIGNIFICANCE none

BUILDING MATERIAL - Composition board over frame clapboard



PHOTO DATE 4-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 41 Inkerman StreetARCHITECTCONTRACTORORIGINAL OWNER G. A. JefferyORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1925-26BUILDING MATERIAL brick, texturedSIGNIFICANCE none

PHOTO DATE: 4-1-75

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 47 Inkerman street, north side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1870-75

SIGNIFICANCE none

BUILDING MATERIAL - light yellow brick - painted



PHOTO DATE 4-1-75
~~2773~~

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 71 Inkerman street, north side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1912-14

SIGNIFICANCE none

BUILDING MATERIAL -stucco



PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 77 Inkerman street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870SIGNIFICANCE noneBUILDING MATERIAL composition board

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 85 Inkerman street, north streetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USEDATE OF CONSTRUCTION after 1927 (1940's?)SIGNIFICANCEBUILDING MATERIAL - metal siding

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 87 Inkerman Street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870SIGNIFICANCE noneBUILDING MATERIAL - siding recently applied over stucco.

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 91 Inkerman street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880SIGNIFICANCE noneBUILDING MATERIAL - recently applied siding over
composition board , over stucco.

PHOTO DATE 29-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 6 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890SIGNIFICANCE noneBUILDING MATERIAL - pressed red brick

PHOTO DATE 29-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 12 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870SIGNIFICANCE noneBUILDING MATERIAL - composition board over board and batten

PHOTO DATE 24-6-72

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 16 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900 - enlarged ~~c. 1930~~ 1925-6SIGNIFICANCE noneBUILDING MATERIAL - pressed red brick

PHOTO DATE 10-1-75

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 18 Inkerman street, south side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.1875

SIGNIFICANCE none

BUILDING MATERIAL - ~~pressed red brick~~
~~composition siding over~~ stucco



PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 22 Inkerman Street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900-1910SIGNIFICANCE noneBUILDING MATERIAL pressed red brick

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 28 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1912SIGNIFICANCE noneBUILDING MATERIAL - pressed red brick

PHOTO DATE 4.1.75'

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 36 Inkerman~~x~~ street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1912-14SIGNIFICANCE noneBUILDING MATERIAL - pressed red brick

PHOTO DATE 4-1-75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 40 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900 (Appears to be older house c.1875,
moved to this location)SIGNIFICANCE noneBUILDING MATERIAL - imitation brick siding over stucco-frame

PHOTO DATE 4-1-75

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 42 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1918SIGNIFICANCE noneBUILDING MATERIAL - yellow-tan brick

PHOTO DATE 24.6.74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 44 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain - probably c.1910SIGNIFICANCE noneBUILDING MATERIAL - ~~frame~~ red ~~with~~ brick with stone lintels
and sills

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 46 INKERMAN STREETARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1875SIGNIFICANCE noneMaterial - frame, clapboarded

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 46 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNER Meadowview Baptist MissionORIGINAL USE Church and Sunday schoolDATE OF CONSTRUCTION c.1922SIGNIFICANCE noneBUILDING MATERIAL - frame, pre-fabricated structure

PHOTO DATE

24-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 74 Inkerman StreetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1870BUILDING MATERIAL recently resided over stuccoSIGNIFICANCE none

PHOTO DATE: 4-1-75

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 80 Inkerman Street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880SIGNIFICANCE noneBUILDING MATERIAL - composition over stucco

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 82 Inkerman street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890SIGNIFICANCE noneBUILDING MATERIAL - stucco

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 84 Inkerman street, south side. SE Corner St. ArnaudARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890SIGNIFICANCE noneBUILDING MATERIAL - stucco

PHOTO DATE 24.6.74

ARCHITECTURAL INVENTORYBlock No.
Item.

Page

LOCATION 100 Linkerman Street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sSIGNIFICANCE noneBUILDING MATERIAL - pressed red brick

PHOTO DATE 24-6-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 156 Inkerman StreetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.19 10-14BUILDING MATERIAL pressed red brick, stone lintels and sillsSIGNIFICANCE none

PHOTO DATE: 4.1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 160 Inkerman StreetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL recent siding over board and battenSIGNIFICANCE none

PHOTO DATE: 4-1-75