

Wood

<i>Filename of original image</i>	<i>Page</i>
Wood 16.tif	2
Wood 20.tif	3
Wood 29.tif	4
Wood 26.tif	5
Wood 21.tif	6
Wood 25.tif	7

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 26 WOOD STREETARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900-1910BUILDING MATERIAL red brick, stone lintels and sillsSIGNIFICANCE none

PHOTO DATE:

10-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 20 WOOD STREETARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sBUILDING MATERIAL yellow brick, brick lintelsSIGNIFICANCE limited. house is attractive to a degree but poor site

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 WOOD STREETARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900=1910BUILDING MATERIAL red brick stone lintels and sillsSIGNIFICANCE none

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 26 WOOD STREETARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL red brick, with front chimneySIGNIFICANCE nonePHOTO DATE: 16-7-74
~~11-4-74~~

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 21 Wood StreetARCHITECTCONTRACTORORIGINAL OWNER Leonard ClineORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 25 Wood StreetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL recently applied metal siding over (stucco?)SIGNIFICANCE none

PHOTO DATE: 20-1-75