

Manitoba

<i>Filename of original image</i>	<i>Page</i>
Manitoba 22.tif	2
Manitoba 26.tif	3
Manitoba 32.tif	4
Manitoba 36.tif	5
Manitoba 40.tif	6
Manitoba 44.tif	7
Manitoba 46.tif	8
Manitoba 48.tif	9
Manitoba 52.tif	10
Manitoba 56.tif	11
Manitoba 60.tif	12
Manitoba 66.tif	13
Manitoba 68.tif	14
Manitoba 70.tif	15
Manitoba 74.tif	16
Manitoba 19.tif	17
Manitoba 25.tif	18
Manitoba 29.tif	19
Manitoba 37.tif	20
Manitoba 45.tif	21
Manitoba 49.tif	22
Manitoba 51-53.tif	23
Manitoba 55.tif	24
Manitoba 61.tif	25

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 22 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c. ~~1895-1905~~ 1918BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 26 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880'sBUILDING MATERIAL recently resided with horizontal siding over
stucco? Frame?SIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 32 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1896-1906BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 36 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 18~~7~~5-1895BUILDING MATERIAL pale yellow brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 40 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1896-1906BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 44 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sBUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 46 Manitoba street, northb sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1896-1906BUILDING MATERIAL pressed red brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 48 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890-1900BUILDING MATERIAL pressed red brick

SIGNIFICANCE Priority #4. Unusual decorative treatment of brick four courses form a decorative frieze above the windows and doors. An unusual feature for Brick houses in Guelph.



PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 52 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain age, probably 1880's
extensively remodelled.BUILDING MATERIAL brick and stone veneersSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 56 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1905-1914BUILDING MATERIAL red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 60 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1875-1880BUILDING MATERIAL stuccoSIGNIFICANCE Priority #4. Character, age

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 66 Manitoba street, north sideARCHITECTCONTRACTOR Bracey (brickwork) Lambert (Carpentry)ORIGINAL OWNER M. DuignanORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1875BUILDING MATERIAL local red brick with yellow brick trimSIGNIFICANCE Priority #4. Age, character

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 68 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880'sBUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 6-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 70 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1906.1912BUILDING MATERIAL pressed red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 74 Manitoba street, north sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1876-1882BUILDING MATERIAL pale yellow brickSIGNIFICANCE none

PHOTO DATE: 7-6-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 19 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c1875BUILDING MATERIAL old mottled brickSIGNIFICANCE Priority #4. age, character

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 25 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c1880BUILDING MATERIAL brick veneer sidingSIGNIFICANCE nonr

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sBUILDING MATERIAL recently covered with horizontal siding over(??)SIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 37 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1875-1880BUILDING MATERIAL siding over ?SIGNIFICANCE limitedPHOTO DATE: 16-7-74
Gut

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 45 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1906-1912BUILDING MATERIAL Pressed red brick with stone lintels and sillsSIGNIFICANCE none

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 49 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1906-1912BUILDING MATERIAL pressed red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 51-53 Manitoba street, south sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION 1906-1912BUILDING MATERIAL pressed red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 21-2-75

ARCHITECTURAL INVENTORYBLOCK No. PAGE
ITEM.LOCATION 55 Manitoba street, soith side, SW corner WoodARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1875-1880BUILDING MATERIAL composition sidingSIGNIFICANCE limited

PHOTO DATE: 16-7-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 61 Manitoba street, south side, SE corner WoodARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1875BUILDING MATERIAL composition sidingSIGNIFICANCE limited

PHOTO DATE: 16-7-74