Crawford

| Filename of original image | Page |
|----------------------------|------|
| Crawford 6.tif | 2 |
| Crawford 8.tif | 3 |
| Crawford 9.tif | 4 |
| Crawford 7.tif | 5 |

BLOCK No. PAGE ITEM.

LOCATION 6 CRACUTERO

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION 1918- 1918

BUILDING MATERIAL brick

SIGNIFICANCE none



PHOTO DATE: 2-7-75

BLOCK No. PAGE ITEM.

LOCATION & CRACUFORD

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION about 1917-22

BUILDING MATERIAL brick with stuccoed second story.

SIGNIFICANCE none



PHOTO DATE: 2.7.75

BLOCK No. PAGE

LOCATION 9 CRAWFORD

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c.194-20

BUILDING MATERIAL

brick

SIGNIFICANCE none



PHOTO DATE: 2-7-75

BLOCK No. PAGE ITEM.

LOCATION 7 CRAWFORD

ARCHITECT

CONTRACTOR

ORIGINAL OWNER Prof. R. R. Graham

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c. 1915-16

BUILDING MATERIAL brick

SIGNIFICANCE none




PHOTO DATE: 2-7-75